

1965 APR 12 21 36Z

13 APR 1965

[illegible]

-2-

ARE PRESENT THROUGHOUT THE MISSION. SHORT, DIAGONAL, MINUS DENSITY STREAKS THAT RESEMBLE STATIC MARKS ARE SPACED ABOUT 3.0" APART AND POSITIONED ABOUT 1.2" FROM THE OUTBOARD EDGE OF THE FILM FROM FRAME 020 TO 050. EMULSION DIGS ARE PRESENT ON THE LAST FRAME OF MOST PARTS. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1892 WITH ASSOCIATED STATIC MARKS ON 1894. BECAUSE THERE WAS NO TAPE SECURING THE LEADER ON THE HEAD OF EACH PART, EXTREME CARE HAD TO BE EXERCISED TO PREVENT DAMAGE TO THE FILM WHEN EXTRACTING THE REEL OF FILM FROM THE CAN.

D. BOTH SIDES: EVIDENCE OF EDGE STATIC IS PRESENT ALONG BOTH SIDES OF THE FILM THROUGHOUT THE MISSION. THE TITLED FRAMES ARE NUMBERED CONSECUTIVELY FROM 0000 TO 2344 ON THE 9L SIDE AND THERE IS ONE ADDITIONAL FRAME ON THE 9R SIDE.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS DURING THE MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS COVERAGE IS LESS THAN 10 PERCENT OF THE MISSION.

GP-1

S E C R E T

--END OF MESSAGE--